

# Oil Field Environmental Incident Summary

**Incident:** 20150205115817      **Date/Time of Notice:** 02/05/2015 11:58  
**Responsible Party:** FIDELITY EXPLORATION & PRODUCTION COMPANY  
**Well Operator:** FIDELITY EXPLORATION & PRODUCTION COMPANY  
**Well Name:** BARNHART1 20-17H  
**Field Name:** HEART RIVER      **Well File #:** 27394  
**Date Incident:** 2/5/2015      **Time Incident:** 09:15      **Facility ID Number:**  
**County:** STARK      **Twp:** 139      **Rng:** 97      **Sec:** 20      **Qtr:**  
**Location Description:** Driver for Coulee Trucking overfilled truck.

**Submitted By:** Daniel Holli      **Received By:**

**Contact Person:** Daniel Holli  
1801 CALIFORNIA STREET  
SUITE 2500  
DENVER, CO 80202

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.5 Mile

**Distance Nearest Water Well:**

**Type of Incident:** Truck Overflow

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels			4	barrels

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 4/10/2015      **Clean Up Concluded:** 4/8/2015

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Environmental Impacts:**

Soil

**Action Taken or Planned:**

Excavating soil onto plastic for analysis and disposal

**Wastes Disposal Location:** Hexom Disposal

**Agencies Involved:** ND Department of Health

**Updates**

---

**Date:** 2/5/2015      **Status:** Reviewed - Assigned to Other Agency

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Called the contact on the report. He indicated that the spill occurred on the Fidelity well pad and it did not leave the site. This was also reported as a general incident report (3639). NDIC retains oversight.